






## SYSTIMAX® GigaSPEED® X10D 91B Series Cable, 95B Series Cordage, or Xpress® 88 Series Cable –Preparation for Termination



Pull off to the side so that it can  
be trimmed close to the jacket



Twist ends back together  
for connecting hardware  
terminations



Retain original pair positions  
for termination